


PWFB 0625

## CORNER RECORD

Document Number 1158City of BELLFLOWER

County of Los Angeles, California

Brief Legal Description FELSON ST. & PALO VERDE AVE

## CORNER TYPE

Govt. Corner ☐ Control ☒  
 Meander ☐ Property ☐  
 Rancho ☐ Other ☐  
 Date of Survey 9-17-13

## COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29 ☐ NAVD88 ☐  
 Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found & tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND & DESCRIBED ON THE REVERSE OF THIS SHEET.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

SEE PAGE 2

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance

with the Land Surveyors' Act on 10/18/13

Signed Daniel A. Calvillo P.L.S. or R.C.E. No. 8294




## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 07 2014

and examined and filed FEB 10 2014

Signed Curt M. O'Bryan P.L.S. or R.C.E. No. 6388

Title: DEPUTY COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

- FOUND MONUMENT AS NOTED
- ✕ DESTROYED DURING CONSTRUCTION
- ( ) DENOTES REFERENCE MEASUREMENTS PER CSFB 3003/41.

